

Matreial Data Sheet

技术数据表

NFD Composite Material (Jiangsu) Co., Ltd

Hepla® H7100 HD6

Material Description:

Hepla® H7100 HD6 is a unreinforced Polyamide 6 (PA6) product. Characteristics include: High Gravity Compound

General				
Material Status	 Commercial: Active 			
	Asia Pacific		 North America 	
Availability	• Europe		 Latin America 	
	Middle East		 Africa 	
	 High Density 		 Good Processability 	
Features	Chemical Resistant		 Wear Resistant 	
	 Self-Lubricating 			
RoHS Compliance	RoHS Compliant			
Processing Method	 Injection Molding 			
Physical Properties	Typical Value	Unit		Test Metho
Density/Specific Gravity	6	g/cm ³		ASTM D79
Moisture Content	0.2		<u> </u>	
Molding Shrinkage - Flow (3.20 mm)	0.5 to 1	%		ASTM D95
Mechanical Properties	Typical Value	Unit		Test Metho
Tensile Modulus	11905	MPa		ASTM D63
Tensile Strength	58.5	MPa		ASTM D63
Tensile Elongation(Yield)	2 to 2.9	%		ASTM D63
Flexural Modulus	11327	MPa		ASTM D79
Flexural Strength	101.5	MPa		ASTM D7
mpact Properties	Typical Value	Unit		Test Metho
Notched Izod Impact(3.2mm)	42.4	J/m		ASTM D2
Jnnotched Izod Impact(3.2mm)	316	J/m		ASTM D48
lammability	Typical Value	Unit		Test Metho
Flame Rating(1.5mm)	НВ			UL !
rocessing Information	Typical Value	Unit		
njection Pressure	68.9 to 103	MPa		
Processing (Melt) Temp	243 to 279	$^{\circ}\!\mathbb{C}$		
Mold Temperature	54 to 93	$^{\circ}$		
Drying Temperature	82	$^{\circ}$		
Drying Time	2	hr		
Dew Point	-18	$^{\circ}$		

NFD ADVANCED COMPOSITES

Hepla® H7100 HD6

CAUTION/警告!

Before using, read the Molding Guide, Material Safety Data Sheets, and Bulletins available from NFD Advanced Composites Sales offices and Distributors supplied to your company. Caution! During drying, purging and molding, small amounts of hazardous gases and/or particulate matter may be released. These may irritate eyes, nose and throat. Use adequate local exhaust ventilation during thermal processing. To prevent resin decomposition, do not contaminate the resin or exceed the recommended melt temperature or hold-up time. Avoid inhalation or skin and eyes contact. Sweep up and dispose of spilled resin to eliminate slipping hazard. 在使用之前,请阅读NFD公司销售办事处和经销商提供给贵公司的材料成型指南、材料安全数据表和公告。警告! 在干燥、吹扫和成型过程中,少量有害气体或颗粒物质可能会在被释放,这些可能会刺激眼睛,鼻子和喉咙。热处理过程中请注意做好排气通风工作。为防止树脂分解,请勿污染树脂或超过我们为您推荐的熔融温度或时间。请避免吸入或与皮肤、眼睛等接触。清扫和处理溢出的树脂,以消除滑到的危险。

LEGAL NOTICES/法律声明

The figures indicated here are approximate values. They may be affected by different factors, and the user is not released therefore from the obligation of performing checks and trials of his own. The values indicated here have been compiled on the basis of current tests and findings. Any legally binding guarantee of certain properties, or any suitability for a specific application can not be inferred from the present data. For detailed production regulatory information, contact customer service.

上列数据只作参考用途,它们可能会受不同因素的影响,使用者有责任通过实验自行确定材料特性。上述资料根据现有测试得出,对物料特性是否适合某特殊用途及特性不能给予保证,数据也没有任何法律约束力。更多有关详细的产品监管信息,请联系客户服务

COMPANY/公司:

Welcome to NFD, where the concept of "New Formula Designer" is upheld and scientific innovation and production are intertwined. Whether you are a designer, engineer or procurement expert, we can help you expand your business and get new inspiration. We adhere to the core values of credibility and integrity, cooperation, efficiency, and innovation, and always put our customers first. Compared with our competitors, we focus on providing more advanced technical formulation, better quality products, more efficient solutions and more thoughtful after-sales services. We understand the markets, the products, and you even more.

CONTACT:

CHINA/JIANG SU 江苏新孚达复合材料有限公司 NFD Composite Material (Jiangsu) Co., Ltd Email:yanghui@nfdpla.com Internet:www.nfdpla.com

